

Title:

**Magnetron Sputtering/ FCVA C.SY**

Rev No:

0002

Issue Date:

31 Oct 2011

Page:

Page 1 of 4

Prepared by:  
Armin de Vera and Malar

Approved by:  
Asst Prof Jeroen Van Kan

Review Date:  
04 Nov 2011

## 0 Objective:

This Standard Operation Procedure states how Magnetron Sputtering/ FCVA C.SY should be started up and shutting down in a proper manner.

## 1 Responsibilities:

### 2.1 Director / HOD / PI

The Director/HOD/PI has overall responsibility for ensuring a system is established for the safe use of the sputtering machine.

### 2.2 Designated Person

There shall be a designated person to oversee the correct operation and maintenance of the sputtering machine.

a. This person shall periodically inspect the sputter machine to ensure its operational performance.

b. He/she will make necessary arrangements for repair works of the sputtering machine.

d. He/she will report to the Director/HOD/PI unsafe practices by sputtering machine users.

### 2.3 Staff/ Research personnel

a. All users shall attend appropriate training on the safe use of the sputtering machine.

b. Users shall report any injuries, defects or breakdowns to their supervisor.

## 2 Procedures:

**Before using the sputtering machine, release the water in the compressor first**

### 3.0 Releasing water from the compressor\*




Fig. 1 Compressor






Fig. 2 the Valve AV1

\*The compressor is shown in the fig. 1 and located behind the accelerator

 <b>NUS</b> National University of Singapore  <b>CIBA</b> Faculty of Science, Dept of Physic , Centre of Ion Beam Applications		Procedure No:	CIBA/SOP/Eq /004
Title:		Rev No:	0002
<b>Magnetron Sputtering/ FCVA C.SY</b>		Issue Date:	31 Oct 2011
		Page:	Page 2 of 4
Prepared by: Armin de Vera and Malar	Approved by: Asst Prof Jeroen Van Kan	Review Date: 04 Nov 2011	

- Open the valve A a little bit until the water in the injected flow is gone.
- Press the valve B till no water is in the injected air flow.

### **3.1 Sample change Procedure**

- Turn OFF the high vacuum gauge
- Close valve BFV
- Vent chamber by opening Nitrogen valve
- Change the sample (wear mask + gloves)
- Close the vacuum door.
- Close valve AV1 (isolate the TMP)
- Check if the AV1 is really closed by watching if the related LED (red) on and another is off (See fig 2)
- open the valve AV2 (rough out the chamber).


WAIT! Wait for chamber to reach pressure less than  $4.9 \times 10^{-2}$  Torr.

- close valve AV2 (stop roughing chamber)
- Open valve AV1 and check if the LED (green) on.
- Open valve BFV (pump system with TMP).

### **3.2 Sputtering Machine (Cr, Cu and Au targets)**

After pumping the chamber down (usually takes more than 6 hours):

- 3.2. 1 . Switch on the “Hi-Vacuum Trigger” to monitor chamber pressure. When pressure is less than  $1.9 \times 10^{-6}$  Torr, sputtering procedure can begin.
- 3.2. 2 . Close the cooling valves to the FCVA side (8 valves in total).
- 3.2. 3 . Behind the machine, choose the target to sputter by plugging the power cable to either the “right target” or “left target”.
- 3.2. 4 . Open GV1.
- 3.2. 5 . Press the “RUN” key on the mass flow controller labeled “Argon” (press the key shortly; if pressed continuously the controller goes to the fully open mode “8”).
- 3.2. 6 . Adjust the “PCV” manually till the pressure is between 2 to 3mTorr.



- 3.2. 7 . Switch on the MDX power supply at the back.

Title:

**Magnetron Sputtering/ FCVA C.SY**

Rev No:

0002

Issue Date:

31 Oct 2011

Page:

Page 3 of 4

Prepared by:  
Armin de Vera and Malar

Approved by:  
Asst Prof Jeroen Van Kan

Review Date:  
04 Nov 2011

3.2. 8 . Switch on MDX front panel (target power) by pressing OFF first then ON (there is now a plasma).

(Maximum time plasma can be left on is 5 min, after which the target needs time to cool before continuing).

3.2. 9 . Check the power (0.15 kW) and write down the voltage and current.

(New Target ~ 600 V; Old target <200 V (Change target)).

3.2. 1 0 . Turn on substrate rotation.

3.2. 1 1 . Check shutter is covering plasma and turn the substrate to plasma.

3.2. 1 2 . Open shutter for desired exposure time.

3.2. 1 3 . Close the shutter and switch OFF the power (MDX front panel).

3.2. 1 4 . Switch off MDX at the back.

3.2. 1 5 . Press "RUN" key on the mass flow controller (controller displays "OFF").

3.2. 1 6 . Close GV1.

3.2. 1 7 . Fully Open "PCV".

3.2. 1 8 . Open the cooling valves to FCVA side.

### **3.3 FCVA – C and Ti**

After pumping the chamber down (usually takes more than 6 hours):

3.2. 1 . Switch on the Hi trigger to check and monitor the vacuum. When pressure is less than  $1.9 \times 10^{-6}$  Torr, FCVA procedure can begin. Operating pressure should be less than  $5 \times 10^{-5}$ .

3.2. 2 . Close the unused FCVA target cooling valves.

3.2. 3 . Connect the power to the target used.

3.2. 4 . Connect power to the bending system.

3.2. 5 . Turn on the main power supply ON at the back (down the bottom).

3.2. 6 . At the control panel, switch on the power (top panels) for the target and also for the magnet guide.

Title:

**Magnetron Sputtering/ FCVA C.SY**

Rev No:

0002

Issue Date:

31 Oct 2011

Page:

Page 4 of 4

Prepared by:  
Armin de Vera and Malar

Approved by:  
Asst Prof Jeroen Van Kan

Review Date:  
04 Nov 2011

- 3.2. 7 . Switch on the anode trigger (red knob) (arc power supply).
- 3.2. 8 . Strike with a quick movement back and forth.
- 3.2. 9 . Check there is plasma.
- 3.2. 1 0 . Switch on the rotating motor of the substrate holder and turn the sample to the plasma. Keep watch of current – plasma may stop in which case timing needs to stop and new spark needs to be made.
- 3.2. 1 1 . Switch off the anode trigger (red knob) after desired exposure time.
- 3.2. 1 2 . Open the valve for cooling the unused target and the magnet.
- 3.2. 1 3 . Switch off the bending magnet.
- 3.2. 1 4 . Switch off the power for the anode current.
- 3.2. 1 5 . Switch off the Hi-trigger.
- 3.2. 1 6 . Switch off the substrate rotating motor.
- 3.2. 1 7 . If carbon was used, switch off the carbon motor.

**Reference:**

- ✓ The current of the first cabinet is 3.4, 3.0, 11. 95.9-105.
- ✓ The voltage for Ti, Cu and carbon are around 124, 84 and 34 respectively.

**Attention:**

- **Do not leave the machine while it is pumped with the rough pump only.** Machine needs to be left with Turbo pumping chamber (backed with roughing pump).
- High vacuum gauge can only be used for low pressures

**3 References:**

Manuals kept on the cabinet at S7-01-01 beside sputtering machine's control panels.